







Sensitive Sites



BLAST MONITORING - ANNUAL RETURN for 2001

For MT COOT-THA QUARRY

Date Prepared - 24/01/2002

Table: Blast Monitoring Results for 25/2/01 to 24/2/02


Company	Site	Date	Distance	Monitor Location	Vector Sum	Overpressure	Weather
BCC	Mt Coot-tha	29-Jan-01	960	58 Richer Street	0.59	110.7	
BCC	Mt Coot-tha	28-Feb-01	920	58 Richer Street	0.52	106.3	Sunny conditions
BCC	Mt Coot-tha	12-Mar-01	940	58 Richer Street	1.31	108.8	
BCC	Mt Coot-tha	10-Apr-01	920	58 Richer Street	1.35	107.2	Slightly overcast
BCC	Mt Coot-tha	04-May-01	830	58 Richer Street	0.39	106.1	Some cloud cover, sunny conditions
BCC	Mt Coot-tha	22-May-01	1130	58 Richer Street	1.06	118.3	Sunny conditions, wet ground
BCC	Mt Coot-tha	13-Jun-01	690	58 Richer Street	0.62	109.7	Sunny conditions
BCC	Mt Coot-tha	03-Jul-01	1100	58 Richer Street	0.74	110.7	Sunny conditions
BCC	Mt Coot-tha	24-Jul-01	648	58 Richer Street	0.42	113	Fine and sunny
BCC	Mt Coot-tha	28-Aug-01	1030	58 Richer Street	1.114	108.9	
BCC	Mt Coot-tha	18-Sep-01	1100	58 Richer Street	0.47	117	Fine sunny conditions, gusterly southerly winds
BCC	Mt Coot-tha	31-Oct-01	1100	58 Richer Street	0.84	113.8	Moderate gusty southerly winds. Clear sky
BCC	Mt Coot-tha	14-Nov-01	765	58 Richer Street	0.41	106.6	Sunny conditions, SE breeze
BCC	Mt Coot-tha	15-Nov-01	960	58 Richer Street	1.54	114.2	Sunny conditions
BCC	Mt Coot-tha	19-Dec-01	1110	58 Richer Street	0.54	111.7	Fine & sunny conditions
BCC	Mt Coot-tha	04-May-01	620	9 Sir Samuel Griffith Drive	1.69	111.9	Some cloud cover, sunny conditions
BCC	Mt Coot-tha	03-Jul-01	760	9 Sir Samuel Griffith Drive	5.05	113.8	Sunny conditions
BCC	Mt Coot-tha	29-Jan-01	790	End of Sussex Street	2.86	119.4	
BCC	Mt Coot-tha	28-Feb-01	690	End of Sussex Street	3.86	107.3	Sunny conditions
BCC	Mt Coot-tha	12-Mar-01	805	End of Sussex Street	2.69	115.9	
BCC	Mt Coot-tha	10-Apr-01	800	End of Sussex Street	4.42	114	Slightly overcast
BCC	Mt Coot-tha	04-May-01	710	End of Sussex Street	1.33	108.9	Some cloud cover, sunny conditions
BCC	Mt Coot-tha	22-May-01	750	End of Sussex Street	3.7	114.8	Sunny conditions, wet ground
BCC	Mt Coot-tha	13-Jun-01	690	End of Sussex Street	Not Recorded	Not Recorded	Sunny conditions
BCC	Mt Coot-tha	03-Jul-01	750	End of Sussex Street	2.61	111.7	Sunny conditions
BCC	Mt Coot-tha	24-Jul-01	750	End of Sussex Street	4.04	114.6	Fine and sunny
BCC	Mt Coot-tha	28-Aug-01	700	End of Sussex Street	5.15	108.6	
BCC	Mt Coot-tha	18-Sep-01	750	End of Sussex Street	3.953	112	Fine sunny conditions, gusterly southerly winds
BCC	Mt Coot-tha	31-Oct-01	750	End of Sussex Street	2.26	109.8	Moderate gusty southerly winds. Clear sky
BCC	Mt Coot-tha	14-Nov-01	765	End of Sussex Street	0.88	109.6	Sunny conditions, SE breeze
BCC	Mt Coot-tha	15-Nov-01	765	End of Sussex Street	6.49	114.9	Sunny conditions
BCC	Mt Coot-tha	19-Dec-01	770	End of Sussex Street	1.34	115.3	Fine & sunny conditions
BCC	Mt Coot-tha	29-Jan-01	470	Quarry Office	2.88	126	
BCC	Mt Coot-tha	28-Feb-01	480	Quarry Office	3.25	120.8	Sunny conditions
BCC	Mt Coot-tha	12-Mar-01	460	Quarry Office	4.25	121.7	
BCC	Mt Coot-tha	10-Apr-01	460	Quarry Office	5.96	125	Slightly overcast
BCC	Mt Coot-tha	04-May-01	300	Quarry Office	3.25	126	Some cloud cover, sunny conditions
BCC	Mt Coot-tha	13-Jun-01	220	Quarry Office	2.63	126.3	Sunny conditions
BCC	Mt Coot-tha	03-Jul-01	650	Quarry Office	1	124.1	Sunny conditions
BCC	Mt Coot-tha	18-Sep-01	612	Quarry Office	1.48	131.3	Fine sunny conditions, gusterly southerly winds
BCC	Mt Coot-tha	31-Oct-01	-	Quarry Office	Inable to retrieve		Moderate gusty southerly winds. Clear sky
BCC	Mt Coot-tha	14-Nov-01	230	Quarry Office	3.27	123.3	Sunny conditions, SE breeze
BCC	Mt Coot-tha	15-Nov-01	570	Quarry Office	5.26	130	Sunny conditions
BCC	Mt Coot-tha	19-Dec-01	600	Quarry Office	1.36	126.5	Fine & sunny conditions

SENSITIVE SITES - RESULTS OK


Non - SENSITIVE SITE

Sensitive Sites


Blast Monitoring 2001 @ 58 Richer St




Blast Monitoring 2001 @ 58 Richer St




Blast Monitoring 2001 @ end of Sussex St




Blast Monitoring 2001 @ end of Sussex St



Blast Monitoring 2001 @ Sir Samuel Griffith Dr



Blast Monitoring 2001 - 9 Sir Samuel Griffith Dr



Non Sensitive Sites

