

GROUNDWATER TECHNOLOGY

AC.N. 003 931 057

Groundwater Technology Australia Pty Limited
Unit 5/31 Thompson Street, Bowen Hills QLD 4006 Australia

Telephone: (07) 252 5711 Fax: (07) 252 5712

ENVIRONMENTAL SITE ASSESSMENT

BP GYMPIE
TOZER STREET
GYMPIE, QUEENSLAND
March 1993.

Presented to:
BP Australia Ltd.
BP House
193 North Quay
Brisbane, Queensland 4000

Prepared by:

sch4p4(6) Personal information

Environmental Scientist

sch4p4(6) Personal information

Project Manager

Our Ref: R314/B7162

April 1993

Dedicated to Environmental Solutions

TABLE OF CONTENTS

PROPERTY DESCRIPTION	i
EXECUTIVE SUMMARY	ii
1. INTRODUCTION	1
1.1 Objectives	1
1.2 Scope of Work	1
2. BACKGROUND INFORMATION	2
2.1 Site Description	2
2.2 Site History	2
2.3 Site Inspection	2
2.4 Regional Geology and Hydrogeology	3
3. ENVIRONMENTAL INVESTIGATION	3
3.1 Soil Gas Survey	3
3.2 Drilling Programme	3
3.3 Laboratory Analysis	4
4. RESULTS	4
4.1 Site Geology and Hydrogeology	4
4.2 Extent and Distribution of Hydrocarbons	4
4.2.1 Vapour Phase Hydrocarbons	5
4.2.2 Adsorbed Phase Hydrocarbons	5
4.2.3 Separate and Dissolved Phase Hydrocarbons	6
4.3 Extent and Distribution of Lead	6
5. CONCLUSIONS	7
6. REFERENCES	8

TABLE OF CONTENTS (continued)

List of Figures

FIGURE 1	-	Site Location Map	Follows Page 1
FIGURE 2	-	Site Plan	Follows Page 2

List of Tables

TABLE 1	-	Soil Sample Analysis Results	Page 5
---------	---	--	--------

List of Appendices

APPENDIX A	-	Land Title Documents
APPENDIX B	-	Site Photographs
APPENDIX C	-	Soil Gas Survey Data
APPENDIX D	-	Methodology
APPENDIX E	-	Drill Logs
APPENDIX F	-	Laboratory Analysis Reports

PROPERTY DESCRIPTION

Local authority:

Gympie City Council

Information Provided by:

KAMS Management Service,
P.O. 296,
EVERTON PARK. QLD. 4053.

Telephone:(07) 355 3134

Site:

BP Gympie,
Tozer Street,
Gympie, Queensland. 4570.

Lot - on - Plan Description:

Lot(s) L2/MCH5328, L1.3/MPH14207, L1/MPH23976, L3/MPH24262
Miners Homestead No. 144, Gympie Mining District, Parish of Gympie.

Name and Postal Address of Owner:

Queensco Foods Co-operative
Association Ltd.,
P.O. Box 2,
GYMPIE, QLD. 4570

Prescribed Purpose:

Petroleum Depot/Service Station

Current Zoning:

20 Industry/service station

Proposed Zoning:

No Proposed Change

Release

EXECUTIVE SUMMARY

BP Australia Ltd. contracted Groundwater Technology Australia Pty. Ltd. to complete an environmental site assessment at the BP Depot/Service Station, Tozer Street, Gympie, Queensland. BP Australia is undertaking this work as part of an ongoing assessment of petroleum facilities in Queensland.

Historical details of the site were not available at the time of site assessment. The site is located on an old gold mining lease.

The site is located on a shale ridge with siltstone and slate components. Soils are very shallow overlying a weathered bedrock profile. Groundwater was not encountered during assessment. QWRC Bundaberg office indicated that bore usage in close proximity to the site is unlikely.

Hydrocarbon concentrations above CHEM Unit investigation thresholds were only present in one soil sampled on site (SB2 1.0m). This sample was analysed by non-NATA registered laboratory. Soil samples from above and below this depth contained hydrocarbon concentrations below CHEM Unit investigation thresholds. SB2 was drilled at the point where the spoon drain meets the site boundary.

Results of the site assessment do not indicate that major hydrocarbon impact of the subsurface has occurred on site.

Release

1. INTRODUCTION

BP Australia Ltd. contracted Groundwater Technology Australia Pty. Ltd. to complete an environmental site assessment at the BP Depot/Service Station, Tozer Street, Gympie, Queensland (Figure 1). Land title documents are presented in Appendix A. BP Australia is undertaking this work as part of an ongoing assessment of petroleum facilities in Queensland.

1.1 Objectives




The objectives of this work were to:

- provide an initial estimate of the extent and distribution of hydrocarbons and lead (if any) at the site,
- identify potential sources and receptors of hydrocarbons or lead.

1.2 Scope of Work

The scope of work included:

- collection of background data,
- completion of a soil gas survey,
- drilling of soil borings with hollow stem auger equipped drill rig,
- collection of selected soil samples and field screening,
- laboratory analyses of selected soil samples,
- preparation of report.



**GROUNDWATER
TECHNOLOGY**

**BP AUSTRALIA LTD
BP GYMPIE DEPOT**

Release

SITE LOCATION MAP

Data by: CD	Date: February 1993	Job No: B7162
Drawn by:	Scale: 1:50 000	Figure No: 1

2. BACKGROUND INFORMATION

2.1 Site Description

The petroleum storage and retail facility is part of a dairy goods processing factory. The site is located on a shale ridge. Surrounding land is undulating and gently undulating. The site slopes from the south west down to the north east in terraces. Land drops away rapidly along the north east edge of the forecourt. Grazing land is located down slope. Details of tank locations are shown on Figure 2 (Site Map).


2.2 Site History

Title search details indicate that the site is owned by Queensco Food Co-operative Association Limited. The operational history of the site is not known. The land was previously a gold mining lease.

Approximately 400 litres of motor spirit was spilled in the vicinity of the tanks/pumps, approximately one month before assessment. Motor spirit flowed along a shallow drain at the edge of the forecourt and then off-site. Hydrocarbon odours were noted at the time of spillage up to 400 metres away in Tozer Lane.

2.3 Site Inspection

Site inspection was completed on 1 February, 1993. The site is mainly surfaced with asphalt. No major hydrocarbon staining was observed. Photographs taken at the time of site inspection and assessment are presented in Appendix B.




LEGEND

- 10 VAPOUR POINTS
- SB1 SOIL BORING

SITE PLAN BP SERVICE STATION TOZER STREET GYMPIE QUEENSLAND

2.5 0 2.5 5.0 7.5 10 12.5 metres
APPROX. SCALE ONLY



GROUNDWATER
TECHNOLOGY

Data by: C.D./I.B.F.

Figure No: 2

Date: FEBRUARY 1993

Job No: B7162

2.4 Regional Geology and Hydrogeology

Interpretation of the 1:250 000 Gympie Geology Sheet SG5610 indicates that the site overlies Gympie Group rocks of Permian Age. The Gympie Group is composed of andesite, agglomerate, rhyolite, shale, siltstone, conglomerate, limestone and greywacke. The Gympie area is characterised by common faulting and associated mineralisation. Underground gold mining has occurred in close proximity to the site.

Queensland Water Resources Commission (QWRC) Bundaberg office indicated that bore usage within close proximity to the site is unlikely. Gympie town water supply is drawn from the Mary River.

3. ENVIRONMENTAL INVESTIGATION

3.1 Soil Gas Survey

A soil gas survey comprising 23 vapour points was completed on 1 February, 1993. Vapour points were located to evaluate areas of potential hydrocarbon impact and migration (tanks, drum store, gantry and site boundaries). The location of vapour points are shown on Figure 2. Soil gas survey results are presented in Appendix C. Soil gas survey methodology is detailed in Appendix D.

3.2 Drilling Programme

Four soil borings (SB1 to SB4) were drilled on 2 & 3 February, 1993 using a drill rig equipped with hollow stem augers. Soil samples collected during drilling were field screened for volatile organic compound (VOC) concentrations and selected samples were sent for laboratory analysis. Sampling protocols are detailed in Appendix D. Locations of monitoring wells are shown on Figure 2 (Site Plan). Details of the soil profile encountered and VOC recordings are shown on drill logs (Appendix E).

3.3 Laboratory Analysis

Selected soil samples were sent to a National Association of Testing Authorities (NATA) registered laboratory for analysis for total petroleum hydrocarbons (TPH), constituent hydrocarbon chain length groups, benzene, toluene, xylene, ethyl benzene (BTXE) and total lead. Sampling and analysis protocols are presented in Appendix D.

Additional samples were sent to Groundwater Technology Australia's laboratory. The laboratory is not currently NATA registered. Sample results are included to provide extra data.

4. RESULTS

4.1 Site Geology and Hydrogeology

The soil profile within four soil borings was composed broadly of roadbase and/or silty clay overlying weathered siltstone. Within SB1, SB2 and SB4 the weathered siltstone displayed a slaty cleavage dipping to the north east at approximately 45°. Permeability along the cleavage/fractures is likely to be relatively high. Weathered siltstone overlies bedrock (probably firm siltstone) which was indicated by auger refusal at 4.0 metres in SB1 and SB2 and > 5.8 metres in SB4. Groundwater was not encountered within the completed scope of work. Given the site location on a rise and the permeability of site geology, it is not expected that shallow groundwater is present. Full details of strata encountered on site are shown on drill logs Appendix E).

4.2 Extent and Distribution of Hydrocarbons

Subsurface hydrocarbons occur primarily in the following four phases.

1. Vapour phase hydrocarbons in the soil pore space.
2. Adsorbed phase hydrocarbons in the soil matrix.
3. Separate phase hydrocarbons on the groundwater table.
4. Dissolved phase hydrocarbons in the groundwater.

4.2.1 Vapour Phase Hydrocarbons

Soil gas survey indicated that elevated VOC concentrations were present in the vicinity of the:

- bunded tank area;
- shallow drain below bunded area leading off site;
- area down gradient of product pumps;

The scope of the soil gas survey was limited due to shallow rocky strata.

4.2.2 Adsorbed Phase Hydrocarbons

Laboratory analysis results are summarised below in Table 1. Laboratory reports are presented in Appendix F.

TABLE 1:
Soil Sample Laboratory Results
Samples Collected on 2 & 3 February, 1993
Results in parts per million (ppm)

Sample	MW	Depth	TPH	C ₈ -C ₉	C ₁₀ -C ₁₄	C ₁₅ -C ₂₀	C ₂₁ -C ₃₀	B	T	X	E	Pb
IF013	SB1	0.5m	8.6	ND	ND	ND	ND	ND	ND	0.8	ND	14
IF015	SB1	3.0m	ND	ND	ND	ND	ND	ND	ND	ND	ND	17
IF017	SB2	0.5m	46.9	ND	13.2	33.6	ND	ND	ND	ND	ND	14
IF019	SB2	3.5m	ND	ND	ND	ND	ND	ND	ND	ND	ND	16
IF021	SB3	2.0m	ND	ND	ND	ND	ND	ND	ND	ND	ND	16
IF024	SB4	2.5m	ND	ND	ND	ND	ND	ND	ND	ND	ND	150
IF025	SB4	4.0m	ND	ND	ND	ND	ND	ND	ND	ND	ND	15
IF016*	SB1	4.0m	0.1	ND	ND	ND	ND	ND	ND	ND	0.1	21
IF018*	SB2	1.0m	1837	ND	465	1372	ND	ND	ND	ND	ND	53
IF020*	SB3	0.5m	56	ND	33	23	ND	ND	ND	ND	ND	79
Method Detection Limits			5	5	5	5	5	0.5	0.5	0.5	0.5	4
Regulatory Thresholds - CHEM Unit				C ₅ -C ₁₀	C ₁₀ -C ₁₆	C ₁₇ -C ₃₀		MAH's				
Draft March 1991				100	100	1000		7				200
January 1992								1				300

TPH = total petroleum hydrocarbons; B = benzene; T = toluene; X = xylene; E = ethyl benzene; MAH = monocyclic aromatic hydrocarbons(BTXE); ND = below method detection limits. Concentrations above regulatory thresholds are highlighted. *Results from non-NATA registered Groundwater Technology Australia laboratory.

Hydrocarbon concentrations were below CHEM Unit (Draft 1991 & 1992) investigation thresholds in all soil samples analysed by a NATA registered laboratory. A VOC concentration of 500 ppm was recorded at 0.5 metres in SB1. Laboratory analysis of this sample returned a TPH concentration of 8.6 ppm. VOC concentration decreased in SB1 with depth below 0.5 metres. VOC concentrations in other soil borings were all < 50 ppm.

One soil sample collected from SB2 1.0m (analysed by non NATA registered laboratory) contained hydrocarbon concentrations above CHEM Unit investigation thresholds. Soil samples collected from above and below one metre depth in SB2 contained hydrocarbon concentrations below analysis method detection limits/CHEM Unit investigation thresholds.

4.2.3 Separate and Dissolved Phase Hydrocarbons

No groundwater was encountered in boreholes drilled on site. No sampling of groundwater was carried out within the scope of assessment. Separate phase hydrocarbons were not observed at anytime during assessment.

4.3 Extent and Distribution of Lead

Total lead concentrations in all soil samples analysed were below 150 ppm. CHEM Unit (1992) investigation thresholds were not exceeded.

5. CONCLUSIONS

Based on the results of investigations completed at the site Groundwater Technology Australia conclude the following;

- BP Australia Ltd operate petroleum storage and distribution facilities on the site which is owned by Queensco Foods Cooperative. The land was previously a gold mining lease.
- The site is located on a ridge with very shallow soils and roadbase overlying weathered siltstone and bedrock. Groundwater was not encountered during assessment. QWRC Bundaberg office indicated that bore usage in close proximity to the site is unlikely.
- Hydrocarbon compound concentrations in the C₁₀ - C₂₈ carbon chain length range were above CHEM Unit investigation thresholds in one soil sample collected at 1.0m in SB2. Soil samples from above and below this depth contained hydrocarbon concentrations below CHEM Unit investigation thresholds.
- SB2 was located at the point where the spoon drain meets the site boundary. Soil gas survey results down slope indicate decreasing VOC concentrations in the shallow subsurface with distance away from SB2.
- Results of the site assessment indicate that no major hydrocarbon impact of the subsurface has occurred on site.

6. REFERENCES

Chemical Hazards and Emergency Management (CHEM) Unit (1992). Guidelines for the Assessment of Contaminated Land in Queensland. Bureau of Emergency Services. Government Printer Queensland.

Chemical Hazards and Emergency Management (CHEM) Unit (1991). Draft Guidelines for Assessment of Contaminated Land in Queensland. Bureau of Emergency Services. Government Printer Queensland.

Geological Survey of Queensland (1981). Gympie 1:250,000 Geological series, Sheet SG56-10.

Queensland Topographic Survey (1980). Gympie 1:50,000 Topographic series, R733 Sheet 9445V.

APPENDIX A
LAND TITLE DOCUMENTS

Our Ref: R314/B7162

April 1993

PAGE 1 DEPARTMENT OF LANDS, QUEENSLAND - ENQUIRY VGTVAL-384
 Valn-No: 502 3669/00000 Ref No : 3313 Fee : LB Trans No: 02
 L/Auth : GYMPIE Map Ref : 9445-42422-3 Flood : N Water : Y
 Address: Land Use: 3500 Zoning: 20 Sewerage: Y
 of Prop TOZER ST S.11(1)7: N Division: 04
 GYMPIE 4570
 Owner : QUEENSCO FOODS CO-OPERATIVE Sale: D/G
 O/C 01 ASSOCIATION LTD Date: 25/06/92
 PO BOX 2 Amt :
 GYMPIE 4570
 Desc : L2/MCH5328 & L1,3/MPH14207 & L1/MPH23976 & L3/
 MPH24262:FAR GYMPIE Area: 9.11 HA

Effect	Valn	Unimproved	Former U/V	Freehold	Issued	Auth
30/06/91	31/03/90	\$ 100000	\$ 100000	\$ 0	24/09/90	02
30/06/93	31/03/92	\$ 180000	\$ 100000	\$ 0	28/09/92	

f1=exit f3=menu f5=next valn f7=page trans f9 =page CONT f11=page return
 f2=refresh f4=list f6=prev valn f8=page hist f10=page one f12=help 50

B. P. GYMPIE

MINER'S HOMESTEAD No. 144

GYMPIE MINING DISTRICT
Gympie FIELD.

Applicant: sch4p4(6) Personal information

Date of Application: 12-7-1873

Lease Issued: 26-2-1874 Dup. Reg.

Area: 25 ac. 5 rd. 16 per. 53

Locality: 20 2 53

Survey Fee...

Mileage...

Traverse...

CANCELLED ON 19-1-89

PURSUANT TO SECT. 28(5)(b) OF MINER'S
HOMESTEAD LEASES ACT.

SUBDIV.	DATE.	NOW SEE M.H. (P.L.) NOS.	TO WHOM TRANSFERRED.
1	9.5.98	12384	The Gympie Central Dairymen's Co. Ltd
2	15.7.99	3372	Peter Green
3	18.6.07	183	Wide Bay Co-op. Dairy Co. Ltd

DATE.

TRANSFERS.

TRANSFERS.

23.8.98 The Licensed Victuallers
Brewery Co. of Gympie Ltd
14.8.06 Thomas Bennett Ashton
13.5.97 James Byrne Hall, Official
Trustee in Liquidation
11. The Wide Bay Co-operative Dairy
16.12.35 The Wide Bay Co-operative
Dairy Association Limited
The Queensland Farmers Co-operative
Associations Limited (Dented)
Queensland Foods Co-operative
Association Limited (Dented)

For Subleases, Easements, etc. see attached Card.

FIELD:

Published on DES Dis
RTI Act 2009

MINING DISTRICT
FIELD

Locality: Lot No. 1 on Plan Ctl. No. MCW 5398 (Subdivision of M.H. 4-164)

Date for Determ. C/V.

Date of Request to Subdivide 4.2.85

Date of Approval 13.12.88

Duplicate Lease

Vol. 445

Fol. 102

Lessee: Quezon Road Co-operative
Association Limited

Transfers

Transferees

Date _____

13-2-5

sch4p4(6) Personal information

Lease Issued.....19.1.89

[illegible]

Cost Printer, Brisbane 19/11/76

~~CONFIDENTIAL~~ LEASE

9193

MINING DISTRICT

Sample FIELD

Locality: Lot No.

2

on Plan Cst. No. ENC H 5308 (Subdivision of M.H. C. 144)

(Subdivision of M.H. L. 144

...

SECRET

4.2.88

13.12.85

Duplicate Lease

Vol. 445

19.1.85

Fol. 111

Lessee Quaranta Trade Co-operative
Associations Limited

Transfers

Date

Transfemes

Area of Lease

Adjust. to Area

Miscellaneous Dealings

7.952W

CANCELLED ON 25/6/92
 PURSUANT TO SECTION 8(3) OF
 MINING TITLES FREEHOLDING ACT 1930-1969

84 131

Govt Printer, B'nhang 19/11 14.36

No. 9193

Group is: FIELD

[illegible]

MINER'S HOMESTEAD. **GYMPIE MINING DISTRICT**

SUBDIVISION No. 1 OF NO. Subdivision 2 of LAL 66 Gympie FIELD.

TRANSFERS.	
DATE.	TRANSFERRER.
9/11/88	The Queensland Farmers co-operative Association Limited.
11-7-88	Quenoco Foods Co-operative Association Limited (Parted).

Transferee: The Wide Bay Co-operative Dairy Association Ltd

Date Transferred: 28. 6. 1989

"Approved: 6. 10. 1989

Transferror: sch4p4(6) Personal information

Area: 2 ac. rd. per. Ac, 278

Lease Issued: 1. 12. 1939 Dup. Reg. Vol. 35

Description: _____

No-sub.	Date.	Area.	To whom Transferred

CANCELLED ON 25/6/92

PURSUANT TO SECTION 8(3) **OF**

MINING TITLES FREEHOLDING ACT 1980-1989

For Subleases, Easements, etc see attached card

DL

SUBLEASES, EASEMENTS, ETC. MITH 1/2/66, GYMPIE	
1	Sublease of part containing 39.2 pers (no. 201/71) to Amoco Australia Pty. Limited for 10 years from 16.6.1970 - folio (22) of file
2	Easement no 202/71 in favour of sublease under sublease no. 201/71 registered at Lands Office, Gympie, on 26.10.71 - see folio (23) of lease file
3	Easement no 204/71 in favour of sublease under sublease no 201/71 registered at Lands Office, Gympie, on 26.10.71 - see folio (23) of lease file
4	Sub-sublease (no. 221/71) over part containing 39.2 pers from Amoco Australia Pty. Limited to The Wide Bay Co-operative Dairy Association Limited for 10 years less one day from 16.6.1970 - folio (25).

12'

MINER'S HOMES LEAD. **GYMPIE MINING DISTRICT**

SUBDIVISION No. 1 OF No. 144 FIELD.

Transferee: The Gympie Central Mining Company Limited

Date Transferred: 9. 5. 1898

Transferror: [Redacted]

Area: + 1 ac. - 2 rd. - 3 1/2 per.

Lease Issued: 12. 4. 1901 Dup. Reg.: Vol. 94

Description: 8. 9. 1929

Re-sub.	Date.	Area.	To whom Transferred.

For Subleases, Easements, etc. see attached card

19

Gympie

TRANSFERS.

DATE.	TRANSFERRED.
19. 10. 00	A. J. Deane & John Reid & William Hutton & D. A. Hutton & J. A. Hutton & J. A. Hutton
19. 10. 00	The Silverwood Dairy Factory Company Limited
25. 4. 07	Wicks Bay Co-operative Dairy Company Limited
20. 11. 24	The Wicks Bay Co-operative Dairy Association Limited (under Primary Producers Co-operative Association Act of 1923)
9-11-87	The Queensland Farmers Co-operative Association Limited (Disted)
11. 7. 88	Queensland Food Co-operative Association Limited (Disted)

EASEMENTS, ETC.

MHL 1/1/64, GYM.

1. Easement No. 202/71 in favour of Sublease under Sublease No. 201/71 registered at
Warden's Office, Kynigie on 26-10-71 - per (23) of file H.1/2/66
2. Easement No. 203/71 in favour of Sublease under Sublease No. 201/71 registered at
Warden's Office, Kynigie on 26-10-71 - per (23) of file H.1/2/66
3. Easement No. 204/71 in favour of Sublease under Sublease No. 201/71 registered at
Warden's Office, Kynigie on 26-10-71 - per (23) of file H.1/2/66

MINER'S HOMESTEAD.		MINING DISTRICT		FIELD.	
SUBDIVISION No. 1		OF No. 144		Lynx	
RENTS				5/10 per acre.	
Year.	Amount.	Year.	Amount.	Year.	Amount.
1899	5 -				
1899/1900	15 -				
1900/1901	5 -				
1901/1902	5 -				
1902/1903	5 -				
1903/1904	5 -				
1904/1905	5 -				
1905/1906	5 -				
1906/1907	5 -				
1907/1908	5 -				
1908/1909	5 -				
1909/1910	5 -				
1910/1911	5 -				
1911/1912	5 -				
1912/1913	5 -				
1913/1914	5 -				
1914/1915	5 -				
1915/1916	5 -				
1916/1917	5 -				
1917/1918	5 -				
1918/1919	5 -				
1919/1920	5 -				
1920/1921	5 -				
1921/1922	5 -				
1922/1923	5 -				
1923/1924	5 -				
1924/1925	5 -				
1925/1926	5 -				
1926/1927	5 -				
1927/1928	5 -				
1928/1929	5 -				
1929/1930	5 -				
1930/1931	5 -				
1931/1932	5 -				
1932/1933	5 -				
1933/1934	5 -				
1934/1935	5 -				
1935/1936	5 -				
1936/1937	5 -				
1937/1938	5 -				
1938/1939	5 -				
1939/1940	5 -				
1940/1941	5 -				
1941/1942	5 -				
1942/1943	5 -				
1943/1944	5 -				
1944/1945	5 -				
1945/1946	5 -				
1946/1947	5 -				
1947/1948	5 -				
1948/1949	5 -				
1949/1950	5 -				
1950/1951	5 -				
1951/1952	5 -				
1952/1953	5 -				
1953/1954	5 -				
1954/1955	5 -				
1955/1956	5 -				
1956/1957	5 -				
1957/1958	5 -				
1958/1959	5 -				
1959/1960	5 -				
1960/1961	5 -				
1961/1962	5 -				
1962/1963	5 -				
1963/1964	5 -				
1964/1965	5 -				
1965/1966	5 -				
1966/1967	5 -				
1967/1968	5 -				
1968/1969	5 -				
1969/1970	5 -				
1970/1971	5 -				
1971/1972	5 -				
1972/1973	5 -				
1973/1974	5 -				
1974/1975	5 -				
1975/1976	5 -				

APPENDIX B
SITE PHOTOGRAPHS


Our Ref: R314/B7162

April 1993

Released



1. BP Gympie service station, shop and pumps.



2. Bulk tanks, drum dock, spoon drain in left of photo, behind car.

APPENDIX C
SOIL GAS SURVEY DATA

Our Ref: R314/B7162

April 1993

Release

TABLE C1:
SOIL GAS SURVEY DATA
1 February, 1993
Volatile Organic Compounds - parts per million

Vapour Point	VOC's - ppm	Vapour Point	VOC's - ppm
1	583	13	20.1
2	301	14	8.5
3	229	15	11.7
4	64.1	16	12.4
5	14.2	17	10.4
6	13.8	18	39.1
7	78.2	19	17.2
8	21.3	20	87.8
9	465	21	74.9
10	706	22	45.0
11	22	23	22.5
12	22.1		

**APPENDIX D
METHODOLOGY**

Our Ref: R314/B7162

April 1993

Relt

D1 SOIL GAS SURVEY

The soil gas survey was conducted to estimate volatile organic compound (VOC) concentrations present in the shallow subsurface at the site.

The soil gas survey utilised a 12mm diameter hand held percussion drill ("slambar") to penetrate the subsurface to depth of one metre. A 1.0 metre stainless steel probe was inserted into the holes. Soil vapours were then drawn through the probe and analysed for VOC concentrations with a hand held air monitor/photoionisation detector (PID)(Photovac MP100, Microtip).

Average VOC concentrations for each survey point were recorded after monitoring for a twenty second interval. The PID was calibrated at the commencement and regularly during the field investigation with a known concentration of iso-butylene span gas.

It should be noted that PID screening of soil vapour provides only a relative indicator of VOC concentrations and does not necessarily represent actual concentrations. The principle compounds of petroleum are detected by this method. Other compounds including some inorganic compounds may also be detected. For the purpose of this report concentrations are attributed solely to hydrocarbon vapour.

D2. BOREHOLE DRILLING, SOIL SAMPLING AND FIELD ANALYSIS.

Soil borings were installed using an Hydrapower 500 drilling rig. A 200mm diameter continuous hollow stem flight auger was used. The drilling was conducted under the direct supervision of a Groundwater Technology Australia geologist who recorded a geological log for each borehole.

Soil borings are used to determine the subsurface conditions and to provide a quantitative assessment of the lateral and vertical extent of any separate, adsorbed or dissolved-phase hydrocarbons.

Soil borings are located to address areas of potential hydrocarbon impact. Potential sources and receptors of hydrocarbon are targeted. Soil gas survey data is used to assist with borehole location. Potential product sources include the tank pit areas, tank fill points, pump islands and product piping. Potential receptors of any contamination include areas downgradient from source areas, areas of increased permeability such as underground utilities, areas upgradient of aquicludes (areas of lower permeability) and areas where there exists a depression in the water table.

Obstructions to drilling such as storage tanks, subsurface piping, overhead power lines, canopies and impenetrable zones also influence the location of soil borings. The locations of soil borings are shown in Figure 2 (Site Plan).

Soil samples were collected at 1.0 metre intervals or at change of strata. To prevent cross contamination from borehole to borehole, augers were cleaned with high pressure water between borings. To prevent cross contamination from sample to sample, the split spoon sampler was cleaned in "Decon 90" solution.

Soil samples were collected directly from the split spoon sampler within the hollow augers. An open ended syringe was used to collect a small "core" of sample weighing approximately five grams. This was immediately transferred to a 25mm x 150mm glass vial with a screw top lid with teflon liner. The glass vial sample is used for analysis of total petroleum hydrocarbons (TPH) and benzene, toluene, ethyl benzene and xylene (BTEX) compounds.

A 100 ml glass jar was filled, sealed and used for total lead analysis. Both vials and jars were stored on ice awaiting laboratory analysis. This reduces volatile loss and bacterial degradation in the samples.

At each sample location a third sample was sealed in a plastic bag and used for texture and mineralogy description. The headspace created was screened on site for VOC's using a PID. The values obtained during the headspace analysis are used as a relative indicator of the adsorbed phase concentrations of volatile organics and do not necessarily represent actual concentrations.

Two samples from SB1, SB2 and Sb4 and one from SB3 were selected and despatched for laboratory analysis.

D5 LABORATORY ANALYSIS

Selected soil samples were submitted to a NATA registered laboratory for analyses. The samples were selected on the basis of the VOC concentrations, evidence of hydrocarbon staining and odour and depth. Where no hydrocarbon staining or odour was apparent, samples collected above and below the water table were selected for laboratory analysis.

Soil samples were analysed for the following:


- Benzene, toluene, ethyl benzene and xylene (BTEX) compounds.
- Total petroleum hydrocarbons (TPH), constituent hydrocarbon chain length groups (C₆-C₉, C₁₀-C₁₄, C₁₅-C₂₈ and C₂₉-C₃₆) by modified method 418.1 Storet No.45501, infra red replaced by capillary gas chromatograph.
- Total lead by APHA 17th Edition 3030C.

APPENDIX E
DRILL LOGS

Our Ref: R314/B7162

April 1993

Release



GROUNDWATER
TECHNOLOGY

Drilling Log

Soil Boring **SB1**

Project BP GYMPIE Owner QUEENSCO
 Location Tozer Street Project No. B7162 Date drilled 02/02/1993
 Surface Elev. _____ Total Hole Depth 4.0 m. Diameter 0.20 m.
 Top of Casing _____ Water Level Initial _____ Static _____
 Screen: Dia _____ Length _____ Type/Size _____
 Casing: Dia _____ Length _____ Type _____
 Filter Pack Material _____ Rig/Core Type Hydrapower 500
 Drilling Company Geoprobe Method Hollow Stem Auger Permit # _____
 Driller sch4p4(6) Pe Log By sch4p4(6) Pers
 Checked By sch4p4(6) License No. _____

See Site Map
For Boring Location

COMMENTS:

* Samples submitted for
laboratory analysis

Depth (m.)	PID (ppm)	Sample ID Blow Count/ % Recovery	Graphic Log	USCS Class.	Description (Color, Texture, Structure) Trace < 10%, Little 10% to 20%, Some 20% to 35%, And 35% to 50%
-1					
0					
0.5	500	0.5 * IF013		Asph Road	ASPHALT; ROADBASE; gravel, grey, high porosity.
1.5	200	1.5 IF014			SILTSTONE; yellow grey, slaty cleavage at approximately 45 degrees to north east. Increased permeability along cleavage/fractures likely.
2					
3	40	3.0 * IF015			
4	50	4.0 * IF016			HOLE TERMINATED AT 4.0 M. (Auger Refusal).
5					
6					
7					
8					

04/01/1993 lithlog-mar92

Page: 1 of 1



GROUNDWATER
TECHNOLOGY

Drilling Log

Soil Boring SB2

Project BP GYMPIE Owner QUEENSCO
Location Tozer Street Project No. B7162 Date drilled 02/02/1993
Surface Elev. _____ Total Hole Depth 4.0 m. Diameter 0.20 m.
Top of Casing _____ Water Level Initial _____ Static _____
Screen: Dia _____ Length _____ Type/Size _____
Casing: Dia _____ Length _____ Type _____
Filter Pack Material _____ Rig/Core Type Hydrapower 500
Drilling Company Geoprobe Method Hollow Stem Auger Permit # _____
Driller sch4p4(6) Pers Log By sch4p4(6) Pers
Checked By sch4p4(6) License No. _____

See Site Map
For Boring Location

COMMENTS:

* Samples submitted for
laboratory analysis.

Depth (m.)	PTD (ppm)	Sample ID Blow Count/ % Recovery	Graphic Log	USCS Class.	Description (Color, Texture, Structure) Trace < 10%, Little 10% to 20%, Some 20% to 35%, And 35% to 50%
-1					
0	50	0.05		CL	SILTY CLAY; fill, brown, damp, plastic,
	10	0.5 * IF017			
1	20	1.0 * IF018			
	5	1.5		Broct	SILTSTONE; yellow grey, slaty cleavage at approximately 45 degrees to north east. Increased permeability along cleavage/fractures likely.
2	3	2.5			
3	3	3.5 * IF019			
4	2	4.0			HOLE TERMINATED AT 4.0 M. (Auger Refusal).
5					
6					
7					
8					

04/01/1993 lithlog-mar92

Page: 1 of 1



Drilling Log

Soil Boring **SB3**

Project BP GYMPIE Owner QUEENSCO
 Location Tozer Street Project No. B7162 Date drilled 03/02/1993
 Surface Elev. _____ Total Hole Depth 3.0 m. Diameter 0.20 m.
 Top of Casing _____ Water Level Initial _____ Static _____
 Screen: Dia _____ Length _____ Type/Size _____
 Casing: Dia _____ Length _____ Type _____
 Filter Pack Material _____ Rig/Core Type Hydrapower 500
 Drilling Company Geoprobe Method Hollow Stem Auger Permit # _____
 Driller sch4p4(6) Pel Log By sch4p4(6) Persor
 Checked By sch4p4(6) F License No. _____

See Site Map
For Boring Location

COMMENTS:

* Samples submitted for
laboratory analysis.

Depth (m.)	PID (ppm)	Sample ID Blow Count/ % Recovery	Graphic Log	USCS Class.	Description (Color, Texture, Structure) Trace < 10%, Little 10% to 20%, Some 20% to 35%, And 35% to 50%
-1					
0	1	0.05		Cher	CHARCOAL & SAND; black, loose, slightly damp, soft, angular,
1	1	0.5 * IF020		Cher	NO CORE RETRIEVED;
2	0	2.0 * IF021		CL	SANDY SILTY CLAY; orange brown, damp, plastic, low permeability.
3	0	3.0		CL	HOLE TERMINATED AT 3.0 M. (Target depth)
4					
5					
6					
7					
8					



Drilling Log

Soil Boring **SB4**



Project BP GYMPIE Owner QUEENSCO
Location Tozer Street Project No. B7162 Date drilled 03/02/1993
Surface Elev. _____ Total Hole Depth 5.8 m. Diameter 0.20 m.
Top of Casing _____ Water Level Initial _____ Static _____
Screen: Dia _____ Length _____ Type/Size _____
Casing: Dia _____ Length _____ Type _____
Filter Pack Material _____ Rig/Core Type Hydrapower 500
Drilling Company Geoprobe Method Hollow Stem Auger Permit # _____
Driller sch4p4(6) Per Log By sch4p4(6) Perso
Checked By sch4p4(6) License No. _____

See Site Map
For Boring Location

COMMENTS:

Groundwater not encountered

* Samples submitted for
laboratory analysis.

Depth (m.)	PID (ppm)	Sample ID Blow Count/ % Recovery	Graphic Log	USCS Class.	Description (Color, Texture, Structure) Trace < 10%, Little 10% to 20%, Some 20% to 35%, And 35% to 50%
-1					
0	0	0.5 IF023		Asph Base	ASPHALT; ROADBASE; blue metal gravel.
1					FILL; silty sandy clay, with bricks, rocks, charcoal, loose and plastic, porous.
2				Fill	
3	0	2.5 * IF024			
4	0	4.0 * IF025			SILTSTONE; yellow grey, slaty cleavage at approximately 45 degrees to north east. Increased permeability along cleavage/fractures likely.
5				Rock	
6					HOLE TERMINATED AT 5.8 M. (Below target depth; approximately 2 metres below base of fill).
7					
8					

APPENDIX F
LABORATORY ANALYSIS REPORTS

Our Ref: R314/B7162

April 1993



Central Science Laboratory University of Tasmania
 PO Box 252C GPO Hobart 7001 Tasmania
 Telephone (002) 20 2155 Fax (002) 20 2494

NATA

Registered No: 3239

Report Number: GWT0152
 CSL Job No: 93/0011

Date Received: 8/2/93

Date Tested: 8/2/93

Date Reported: 10/2/93

Client:

Test Method: Modified Method 418.1 Storet No. 45501

Quantitation by Infra Red replaced by Capillary Gas Chromatography

Certificate of Analysis

Soils

ID	PROJECT	MOISTURE	DEPTH	TPH GC	C6-C9	C10-C14	C15-C28	C29-C36	BENZ	TOL	XYL	ETH BENZ
IF013	B7162	4.6	SB1-0.5m	8.6	ND	ND	ND	ND	ND	ND	0.8	ND
IF015	B7162	4.1	SB1-3.0m	ND	ND	ND	ND	ND	ND	ND	ND	ND
IF017	B7162	15.1	SB2-0.5m	46.9	ND	13.2	33.6	ND	ND	ND	ND	ND
IF019	B7162	4.9	SB2-3.5m	ND	ND	ND	ND	ND	ND	ND	ND	ND
IF021	B7162	17.1	SB3-2.0m	ND	ND	ND	ND	ND	ND	ND	ND	ND
IF024	B7162	25.1	SB4-2.5m	ND	ND	ND	ND	ND	ND	ND	ND	ND
IF025	B7162	5.0	SB4-4.0m	ND	ND	ND	ND	ND	ND	ND	ND	ND

Detection Limits

Accuracy: 5.00%

5ppm

5ppm

5ppm

5ppm

5ppm

All BTEX 0.5 ppm

ND = Not Detected

This laboratory is registered by the National Association of Testing Authorities Australia.
 The Test(s) reported herein have been performed in accordance with its terms of registration.

This document must not be reproduced except in full.

sch4p4(6) Personal Information

sch4p4(6) Per M.R.A.C.I.

Authorising Chemist.

This laboratory is registered by the National Association of Testing Authorities, Australia. The test(s) reported herein have been performed in accordance with its terms of registration. This document shall not be reproduced except in full.

Central Science Laboratory University of Tasmania				NATA
PO Box 252C GPO Hobart 7001 Tasmania				Registered No 3239
Telephone (002) 20 2155 Fax (002) 20 2494				
Date Received:	8/2/93	Certificate of Analysis		Report Number GWT0152
Date Tested:	10/2/93	Soils (Acid extractable lead)		CSL Job No 93/0011
Date Reported:	11/2/93			
Client:				
Test Method:	APHA 17th Edition 3030 C			
ID	PROJECT	DEPTH	Pb	
IF013	B7162	SB1-0.5m	14	
IF015	B7162	SB1-3.0m	17	
IF017	B7162	SB2-0.5m	14	
IF019	B7162	SB2-3.5m	16	
IF021	B7162	SB3-2.0m	16	
IF024	B7162	SB4-2.5m	150	
IF025	B7162	SB4-4.0m	15	
Detection limits				4ppm
Accuracy:	3.00%	Units:	ppm	ND = Not Detected
This laboratory is registered by the National Association of Testing Authorities Australia.				
The Test(s) reported herein have been performed in accordance with its terms of registration.				
This document must not be reproduced except in full.				
sch4p4(6) Personal information				
Authorising Chemist.				

This Laboratory is registered by the National Association of Testing Authorities, Australia. The test(s) reported herein have been performed in accordance with its terms of registration. This document shall not be reproduced except in full.



Groundwater Technology Australia Pty Limited
A.C.N. 003 931 057
17 Forrester Street, Kingsgrove NSW 2208 Australia
Telephone: (02) 502 4844 Fax: (02) 502 2105

LABORATORY REPORT


LABORATORY REPORT			
CLIENT:	BP Gympie	SAMPLE TYPE:	Soil
JOB NO:	B7162	ANALYTES REQUIRED:	Pb
SUBMITTED BY:	sch4p4(6) Personal	DATE RECEIVED:	10.2.93
TELEPHONE:	(07) 252 5711	DATE ANALYSED:	10.2.93
FAX:	(07) 252 5712	DATE REPORTED:	11.2.93

[illegible]

<u>ANALYST:</u>	sch4p4(6) Personal information
<u>SIGNATURE:</u>	
<u>CHECKED BY</u>	
<u>SIGNATURE:</u>	

UNITS: Soil (mg/kg) ppm

COMMENTS:



LABORATORY REPORT

CLIENT:	SAMPLE TYPE:	Soil
JOB NO: B7162	ANALYTES REQUIRED:	BTEX/TPH
SUBMITTED BY: sch4p4(6) Personal in	DATE RECEIVED:	10.2.93
TELEPHONE: (07) 252 5711	DATE ANALYSED:	BTEX 16/17.2.93 TPH 12.2.93
FAX: (07) 252 5712	DATE REPORTED:	18.2.93

		ANALYTE	Benzene USEPA	Toluene	Ethyl Benzene	Xylenes (Total)	Total BTEX		
		METHOD	USEPA 602, 5030/8020					%RSD	% RECOVERY
		PQL (PPM)	0.1	0.1	0.1	0.1	0.1		
SAMPLE ID	LAB #	MDL (PPM)							
IF 6	083		ND	ND	ND	0.1		3	86
IF018	084		ND	ND	ND	ND			
IF020	085		ND	ND	ND	ND			
		ANALYTE	C ₆ - C ₉	C ₁₀ -C ₁₄	C ₁₅ -C ₂₈	C ₂₉ -C ₃₆		%RSD	% RECOVERY
		METHOD	Modified USEPA 3510/GTEL						
		PQL (PPM)	10	10	10	10			
SAMPLE ID	LAB #	MDL (PPM)							
IF016	083		ND	ND	ND	ND		1	103
IF018	084		ND	465	1372	ND			
IF020	085		ND	33	23	ND			

ANALYST:	sch4p4(6) Personal in	UNITS: BTEX - PPB (Waters) PPM (Soil)
SIGNATURE:		TPH - PPM
CHECKED BY:		COMMENTS:
SIGNATURE:		

GROUNDWATER TECHNOLOGY AUSTRALIA

Unit 5/31 Thompson Street, Bowen Hills,
Qld, Australia 4006
Telephone: (07) 252 5711 Fax: (07) 252 5712

C. IN-OF-CUSTODY RECORD AND ANALYSIS REQUEST

Project Manager: sch4p4(6) Personal information

Phone #: (77) 252 5711

Address: *1000 1/2 N. Main St. Box 1000* FAX #: *607-732-3112*
Box 1000

Project Number: B7162

Project Name:

Project Location:

Sampler Signature:

[illegible]

Relinquished by:

sch4p3(3) Prejudice the protection of an indi

Date Time

OK/2 Sp.

Received by:

Laboratory Samples sent to:

Relinquished by:

Date Time

Received by:

Remarks:

Relinquished by:

21-224

Date Time

Received by Laboratory:

File B